

## Operable Unit 2 (OU2)

Petroleum, Oil, and Lubricants Area, Long-term Coal Storage Pile; Burial Site 1;  
Building 89 Coal Storage Area

During 1996 and 1997, WPAFB upgraded the POL area, abandoning all below ground fuel lines and replacing them with above ground lines. Other project improvements have included storage tank improvements and berm upgrades around the tanks. Due to these recent upgrades and evidence that the fuels are naturally degrading, natural attenuation with long-term monitoring was selected as the remedial action for this site. Semi-annual monitoring demonstrated that natural attenuation is decreasing the contaminate levels. Long-term monitoring is being addressed under the Basewide Monitoring Program. Site investigations indicated remedial actions were not necessary for the other sites within this OU.