

Site Name:	<b>McArthur Lumber &amp; Post</b>		
Street Address:	State Rte 93 N of McArthur		
City:	McArthur	EPA District:	SEDO
County:	Vinton	NFA Type:	90 Day
Acres:	32.51	Audit?	No
MOA track?	N/A	Project ID:	482002060011
NFA Number:	08NFA309	Date CNS Issued:	6/30/2009
Date Received:	9/4/2008		



CORF:	N/A	COAF:	2005, \$742,131; 2004, \$ 230,093	TBA:	N/A
-------	-----	-------	-----------------------------------	------	-----

Certified Professional:	Atul Pandey (CP224)	Certified Lab:	EA Group (CL0015); Pace Analytical Services, Inc. (CL0101); TestAmerica (CL0018)	Volunteer Address:	Vinton County Commissioners Community Development 100 E Main St McArthur, OH 45651; Appalachia Wood, Inc.
-------------------------	---------------------	----------------	--	--------------------	---

History of use:	The property has been used as a wood treatment facility since 1961. Creosote was the primary treatment chemical until 1981, along with petachlorophenol which was used in the late 1960's to 1978. Chemicals such as chromated copper arsenate (CCA) and alkaline copper quaternary (ACQ) are currently used to pressure treat lumber at the facility.		
Chemicals of Concern:	VOCs, SVOCs, TPH, and metals	Applicable Standards:	For commercial/industrial land use and unrestricted potable use of ground water.
Urban Setting Designation?	N/A	Institutional Control(s)/Environmental Covenant:	An Environmental Covenant restricts the property to commercial/industrial land use.
Remedial Activities:	Groundwater contamination was reduced through a series of chemical oxidation applications performed in the Groundwater Remediation Area. Contaminated soil was also removed and disposed of off-site.	Engineering Control(s):	N/A

Operation and Maintenance Agreement?	N/A	Risk Mitigation Plan?	N/A
Proposed Land Use:	Still in use as a wood treatment facility.		